

01807.001647



PATENT

*Cofee \$*

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: )  
CLAUDE LE DANTEC ) : Examiner: Lawrence B. Williams  
Appln. No.: 09/826,148 ) : Art Unit: 2634  
Filed: April 5, 2001 ) :  
For: ENCODING AND DECODING ) :  
METHODS AND DEVICES AND ) :  
SYSTEMS USING THEM ) :  
U.S. Patent No.: 6,993,085 B2 ) :  
Issued: January 31, 2006 ) : September 18, 2006

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

*Certificate*  
*SEP 22 2006*  
*of Correction*

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

01 FC:1811 100.00 0P

SEP 22 2006

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



---

Raymond DiPerna  
Attorney for Patentee  
Registration No. 44,063

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
Facsimile: (212) 218-2200

591709v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,993,085 B2

DATED : January 31, 2006

INVENTOR(S) : CLAUDE LE DANTEC

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) U.S. PATENT DOCUMENTS

“6,621,873 B1 \* 9/2003 Kim et al.” should read --6,621,873 B1 \* 9/2003 Lee et al.--.

COLUMN 1

Line 56, “will” should read --will be--.

COLUMN 5

Line 44, “embodiment;” should read --embodiment; and--; and

Line 46, “proper” should read --properly--.

COLUMN 7

Line 2, “U<sub>1</sub>, U<sub>2</sub>, . . . , U<sub>p<sub>2</sub></sub>,” should read --U<sub>1</sub>, U<sub>2</sub>, . . . , U<sub>p<sub>2</sub></sub>--;

Line 6, “U<sub>i</sub>,” should read --U<sub>i</sub>--; and “V<sub>i</sub>” should read --V<sub>i</sub>--;

Line 7, “U<sub>i</sub>,” should read --U<sub>i</sub>--; and “V<sub>i</sub>” should read --V<sub>i</sub>--;

Line 23, “g<sub>i</sub>(x)” should read --g<sub>i</sub>(x)--;

Line 25, “g<sub>i</sub>(x).” should read --g<sub>i</sub>(x).--; and

Line 57, “U<sub>j</sub>” should read --U<sub>j</sub>--.

COLUMN 8

Line 39, “u” should read --u--; and

Line 65, “sequenceu” should read --sequence u--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,993,085 B2

No. of add'l. copies  
@ 30¢ per page

Staple  
Here  
Only!

PRINTER'S TRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,993,085 B2  
DATED : January 31, 2006  
INVENTOR(S) : CLAUDE LE DANTEC

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 9

Line 14, "r;" should read --r--;  
Line 23, "fromu" should read --from u--;  
Line 41, "U<sub>i</sub>" should read --U<sub>i</sub>--;  
Line 45, "U<sub>i</sub>" should read --U<sub>i</sub>--;  
Line 46, "u<sub>i</sub>" should read --u<sub>i</sub>--;  
Line 51, "sequencesu" should read --sequences u--;  
Line 66, "U<sub>i</sub>;" should read --U<sub>i</sub>--; and  
Line 67, "V<sub>i</sub>;" should read --V<sub>i</sub>--.

## COLUMN 10

Line 10, "U<sub>i</sub>;" should read --U<sub>i</sub>--; and "V<sub>i</sub>;" should read --V<sub>i</sub>--;  
Line 14, "U<sub>i</sub>." should read --U<sub>i</sub>--;  
Line 18, "U<sub>i</sub>" should read --U<sub>i</sub>--;  
Line 19, "u\*" should read --u\*--;  
Line 24, "u\*\*" should read --u\*\*--;  
Line 25, "u," should read --u--;  
Line 27, "u" should read --u--;  
Line 28, "u\*;" should read --u\*--;  
Line 34, "u," should read --u--;  
Line 35, "u" should read --u--;  
Line 45, "sequenceu" should read --sequence u--;  
Line 55, "g<sub>1</sub>(x)," should read --g<sub>1</sub>(x)--;  
Line 56, "h<sub>1</sub>(x)," should read --h<sub>1</sub>(x)--;  
Line 58, "sequencesu" should read --sequences u--;  
Line 59, "/g<sub>1</sub>)," should read --/g<sub>1</sub>)--; and  
Line 62, "sequencesu" should read --sequence u--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,993,085 B2

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,993,085 B2

DATED : January 31, 2006

INVENTOR(S) : CLAUDE LE DANTEC

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11

Line 3, "U'<sub>i</sub>," should read --U'<sub>i</sub>--;  
Line 4, "g<sub>2</sub>(x)," should read --g<sub>2</sub>(x)--;  
Line 5, "h<sub>2</sub>(x)," should read --h<sub>2</sub>(x)--;  
Line 6, "V'<sub>i</sub>," should read --V'<sub>i</sub>--;  
Line 8, "V'<sub>i</sub>(=U'<sub>i</sub>," should read --V'<sub>i</sub>(=U'<sub>i</sub>--;  
Line 11, "V'<sub>j</sub>)" should read --V'<sub>j</sub>)--;  
Line 36, "û" should read --û--;  
Line 38, "û" should read --û--;  
Line 54, "u" should read --u--; and  
Line 67, "Û<sub>j</sub>" should read --Û<sub>j</sub>--.

COLUMN 12

Line 33, "U'<sub>j</sub>)" should read --U'<sub>j</sub>)--;  
Line 34, "U'<sub>j</sub>)" should read --U'<sub>j</sub>)--;  
Line 35, "Û<sub>i</sub>" should read --Û<sub>i</sub>--; and Û'<sub>i</sub>." should read --Û'<sub>i</sub>--;  
Line 53, "û\*" should read --û\*--;  
Line 54, "Û'<sub>i</sub>" should read --Û'<sub>i</sub>--; and  
Line 57, "û," should read --û--.

COLUMN 13

Line 9, "U"<sub>i</sub>" should read --U"<sub>i</sub>--; and  
Line 11, "U'<sub>i</sub>," should read --U'<sub>i</sub>--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,993,085 B2

No. of add'l. copies  
@ 30¢ per page

Staple  
Here  
Only!

PRINTER'S TRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,993,085 B2

DATED : January 31, 2006

INVENTOR(S) : CLAUDE LE DANTEC

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 13

Line 21, "(U<sub>i</sub>) p<sub>1</sub>" should read --(U<sub>i</sub>), p<sub>1</sub>--; and  
Line 31, "(U<sub>i</sub>)," should read --(U<sub>i</sub>),--.

### COLUMN 14

Line 2, "(U<sub>i</sub>)," should read --(U<sub>i</sub>),--;  
Line 15, "(U<sub>i</sub>)," should read --(U<sub>i</sub>),--;  
Line 17, "(U<sub>i</sub>)," should read --(U<sub>i</sub>),--; and  
Line 21, "(U<sub>j</sub>)." should read --(U<sub>j</sub>),--.

### COLUMN 15

Line 15, "(u<sup>\*</sup>);" should read --(u<sup>\*</sup>); and--; and  
Line 48, "(u<sup>\*</sup>);" should read --(u<sup>\*</sup>); and--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,993,085 B2

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,993,085 B2

DATED : January 31, 2006

INVENTOR(S) : CLAUDE LE DANTEC

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) U.S. PATENT DOCUMENTS

“6,621,873 B1 \* 9/2003 Kim et al.” should read --6,621,873 B1 \* 9/2003 Lee et al.--.

COLUMN 1

Line 56, “will” should read --will be--.

COLUMN 5

Line 44, “embodiment;” should read --embodiment; and--; and  
Line 46, “proper” should read --properly--.

COLUMN 7

Line 2, “ $U'_1, U'_2, \dots, U'_{p_2}$ ,” should read -- $\underline{U'_1}, \underline{U'_2}, \dots, \underline{U'_{p_2}}$ --;  
Line 6, “ $U'_i$ ,” should read -- $\underline{U'_i}$ --; and “ $V'_i$ ” should read -- $\underline{V'_i}$ --;  
Line 7, “ $U'_i$ ,” should read -- $\underline{U'_i}$ --; and “ $V'_i$ ” should read -- $\underline{V'_i}$ --;  
Line 23, “ $g_i(x)$ ” should read -- $g_i(x)$ --;  
Line 25, “ $g_i(x)$ .” should read -- $g_i(x)$ --; and  
Line 57, “ $U'_j$ ” should read -- $\underline{U'_j}$ --.

COLUMN 8

Line 39, “ $\hat{u}$ ” should read -- $\hat{u}$ --; and  
Line 65, “sequenceu” should read --sequence u--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,993,085 B2

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,993,085 B2

DATED : January 31, 2006

INVENTOR(S) : CLAUDE LE DANTEC

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 14, "r;" should read --r--;  
Line 23, "fromu" should read --from u--;  
Line 41, "U;" should read --U--;  
Line 45, "U;" should read --U--;  
Line 46, "u;" should read --u--;  
Line 51, "sequencesu" should read --sequences u--;  
Line 66, "U;" should read --U--; and  
Line 67, "V;" should read --V--.

COLUMN 10

Line 10, "U;" should read --U--; and "V;" should read --V--;  
Line 14, "U;" should read --U--;  
Line 18, "U;" should read --U--;  
Line 19, "u," should read --u--;  
Line 24, "u," should read --u--;  
Line 25, "u," should read --u--;  
Line 27, "u," should read --u--;  
Line 28, "u;" should read --u--;  
Line 34, "u," should read --u--;  
Line 35, "u," should read --u--;  
Line 45, "sequenceu" should read --sequence u--;  
Line 55, "g<sub>1</sub>(x)," should read --g<sub>1</sub>(x)--;  
Line 56, "h<sub>1</sub>(x)," should read --h<sub>1</sub>(x)--;  
Line 58, "sequencesu" should read --sequences u--;  
Line 59, "/g<sub>1</sub>)," should read --/g<sub>1</sub>)--; and  
Line 62, "sequencesu" should read --sequence u--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,993,085 B2

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,993,085 B2  
DATED : January 31, 2006  
INVENTOR(S) : CLAUDE LE DANTEC

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11

Line 3, "U'<sub>i</sub>," should read --U'<sub>i</sub>--;  
Line 4, "g<sub>2</sub>(x)," should read --g<sub>2</sub>(x),--;  
Line 5, "h<sub>2</sub>(x)," should read --h<sub>2</sub>(x),--;  
Line 6, "V'<sub>i</sub>," should read --V'<sub>i</sub>--;  
Line 8, "V'<sub>i</sub>(=U'<sub>i</sub>," should read --V'<sub>i</sub>(=U'<sub>i</sub>--;  
Line 11, "V'<sub>i</sub>)" should read --V'<sub>i</sub>--;  
Line 36, "û" should read --û--;  
Line 38, "û" should read --û--;  
Line 54, "u" should read --u--; and  
Line 67, "Û<sub>j</sub>" should read --Û<sub>j</sub>--.

COLUMN 12

Line 33, "U'<sub>j</sub>)" should read --U'<sub>j</sub>--;  
Line 34, "U'<sub>j</sub>)" should read --U'<sub>j</sub>--;  
Line 35, "Û<sub>i</sub>" should read --Û<sub>i</sub>--; andÛ<sub>i</sub>," should read --Û<sub>i</sub>--;  
Line 53, "û\*" should read --û\*--;  
Line 54, "Û<sub>i</sub>" should read --Û<sub>i</sub>--; and  
Line 57, "û," should read --û--.

COLUMN 13

Line 9, "U"<sub>i</sub>" should read --U"<sub>i</sub>--; and  
Line 11, "U'<sub>i</sub>." should read --U'<sub>i</sub>--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,993,085 B2

No. of add'l. copies  
@ 30¢ per page

Staple  
Here  
Only!

PRINTER'S TRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,993,085 B2

DATED : January 31, 2006

INVENTOR(S) : CLAUDE LE DANTEC

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 13

Line 21, "(U<sub>i</sub>) p<sub>1</sub>" should read --(U<sub>i</sub>), p<sub>1</sub>--; and  
Line 31, "(U<sub>i</sub>)," should read --(U<sub>i</sub>),--.

### COLUMN 14

Line 2, "(U<sub>j</sub>)," should read --(U<sub>j</sub>)--;  
Line 15, "(U<sub>j</sub>)," should read --(U<sub>j</sub>),--;  
Line 17, "(U<sub>j</sub>)," should read --(U<sub>j</sub>)--; and  
Line 21, "(U<sub>j</sub>).," should read --(U<sub>j</sub>).--.

### COLUMN 15

Line 15, "(u\*)" should read --(u"); and--; and  
Line 48, "(u\*)" should read --(u"); and--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,993,085 B2

No. of add'l. copies  
@ 30¢ per page